

Område: O3.1 - Ellös, Örusters kommun

Sektion: K1

Analys: Dränerad

File Name: O3\_1K1-drän.slp  
Last Saved Date: 2001-06-07  
Last Saved Time: 11:32:03  
Analysis Method: Bishop  
Direction of Slip Movement: Right to Left  
Slip Surface Option: Grid and Radius

