

Område: O3.1 - Ellös, Örursts kommun

Sektion: K1

Analys: Odränerad

File Name: O3_1K1-odrän.slp
Last Saved Date: 2001-06-07
Last Saved Time: 11:19:22
Analysis Method: Bishop
Direction of Slip Movement: Right to Left
Slip Surface Option: Grid and Radius

