

Område: O1.3 - Henån, Orusts kommun

Sektion: K2

Analys: Dränerad

File Name: O1_3K2-drän.slp
Last Saved Date: 2001-06-07
Last Saved Time: 09:19:25
Analysis Method: Bishop
Direction of Slip Movement: Right to Left
Slip Surface Option: Grid and Radius

