

Område: O1.3 - Henån, Orusts kommun

Sektion: K1

Analys: Dränerad

File Name: O1\_3K1-drän.slp  
Last Saved Date: 2001-06-07  
Last Saved Time: 15:22:02  
Analysis Method: Bishop  
Direction of Slip Movement: Left to Right  
Slip Surface Option: Grid and Radius

